

INCORRECT FIXING OF BRACING PANELS

Purpose

The purpose of this newsflash is to advise building certifiers, designers and builders of the attached Information Bulletin, prepared by James Cook University's Cyclone Testing Station, on the consequences of the incorrect fixing of bracing panels. Flawed fixing can reduce the capacity of a building to resist high winds.

See attachment for further information

Contact

Cyclone Testing Station School of Engineering James Cook University - Qld 4811 Phone: (07) 4781 4476 Fax: (07) 4775 1184 Email: jcu.cts@jcu.edu.au Web: www.eng.jcu.edu.au/cts

DISCLAIMER: The information contained in this Newsflash is provided by the State of Queensland in good faith. The material is general in nature and before relying on the material in any important matter, users should carefully evaluate its accuracy, currency, completeness and relevance for their purpose. It is not intended as a substitute for consulting the relevant legislation or for obtaining appropriate professional advice relevant to your particular circumstances. The State of Queensland cannot accept responsibility or liability for any loss, damage, cost or expense you might incur as a result of the use of or reliance on information contained in this Newsflash. It is not intended to be, and should not be relied upon as the ultimate and/or complete source of information.